

3.5.2 Holy Trinity Fabric Report

Anxiety continues over the proximity and size of the evergreens, in our churchyard, with little hope of reducing their number.

The stone pillars have suffered some erosion and the Town Council has made repairs but not to the standard required of the DAC. This has been reported back.

Holy Trinity is actively investigating a new north-facing roof; quotes have been obtained. It is planned that we investigate applying to trust funds. Sadly, minor repairs are required to the south side where individual tiles have been lost. (The south side roof was replaced in 1997.) It was decided that we should wait until the current trend in stormy weather has ceased before repairs are made.

Regular servicing has been carried out, as appropriate, during the year

Charlotte Tremain
Deputy Warden